



VCCI Council

## Acceptance of Registration of Product Conformity

Company name: Sophos Ltd.  
 Address: The Pentagon, Abingdon Science Park, Abingdon, OX14 3YP UK  
 Responsible person Martin Becker Member number: 3249  
 Department: Product Management Report No.: 2021095663  
 E-mail: Martin.Becker@sophos.com Reporting date: 2022/03/11  
 Contact person Martin Becker Reporting media: online  
 Address: Amalienbadstraße 41/Bau 52, 76227 Karlsruhe, Germany  
 Department: Product Management Status: accepted  
 Phone: +49 (0) 721 255 16 232 Last report No.:  
 FAX: +49 (0) 721 255 16 200 Acceptance No.: 2021067136  
 E-mail: Martin.Becker@sophos.com Sub No.: 1  
 Recipient of Acceptance Notice Acceptance date: 2022/03/14  
 Department: Product Management  
 E-mail: Martin.Becker@sophos.com

|  |  |  |  |
|--|--|--|--|
| Reporting type:                                      | new  |  |  |
| Applied VCCI Rule:                                   | VCCI 32-1  |  |  |
| Classification of Equipment and classification code: | ClassA / Classification code W2  |  |  |
| General Name of Equipment:                           | Sophos Switch  |  |  |
| Product type (Model No.):                            | CS210-48FP   |  |  |
| Member number of a test laboratory:                  | 395  | Bureau Veritas Consumer Products Services, (H.K.) Ltd., Taoyuan Branch |  |
| Name of the testing laboratory:                      |  |  |  |
| Measurement facility registration number:            | Measurement item and Registration No. of Testing facility.   |  | Measurement distance/Reason why not applicable |
|  | 1. Radiated EMI measurement below 1GHz facility  | R-11893  | 10 m   |
|  | 2. Radiated EMI measurement above 1GHz facility  | G-10018  | 3 m  |
|  | 3. Mains port conducted EMI measurement facility   | C-12040  |  |
|  | 4. Conducted EMI measurement for Wired Network port, etc (including Tuner port, Antenna port, etc) | T-11653  |  |
|  | 5. Article 15 registered laboratory  | A-   |  |
|  | 6. This compliance verification test was conducted at the installation site of users.              |  |  |
| Date of testing:                                     | 2021/12/21   |  |  |
| Serial No. of the test report:                       | VBDYS-WTW-P21123296  |  |  |
| Reason for addition/modification:                    |  |  |  |
| VCCI comment:  |  |  |  |